#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-026184

Address: 333 Burma Road **Date Inspected:** 27-Aug-2011

City: Oakland, CA 94607

**Project Name:** SAS Superstructure OSM Arrival Time: 1700 **OSM Departure Time:** 300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** See below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** OBG

### **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for random observations relative to the work being performed.

Bay 19

This QA Inspector observed the following work in progress for Bay 19.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

AB/F QA is identified as Zhong Qi Li.

Welding variables recorded by QA appeared to comply with the approved Welding Procedure Specification (WPS). Listed below are the locations that were identified by this QA inspector. (see photo below)

Components; Bike Path

PCMK: BK9003

Weld No: Lifting Lugs

Welder: 062734

WPS-B-T-2233-ESAB

#### Bay 16

This Caltrans QA Inspector observed at random intervals ZPMC performing heat straightening of hand rails in various locations due to weld distortion and visual indications as identified by ZPMC QC Inspectors. (see photos below)

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.







## **Summary of Conversations:**

"No relevant conversations."

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Leavitt, Kelly	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer